

AAF Guide Technical Bulletin #1.1 (May 2009)

1.1 Update to 2007 AAF Guide to Aluminum Construction

(2009 Amendments to the 2007 Florida Building Code)

Chapter 1

<i>Updated Page/s</i>	<i>Update Reason</i>
p. 1-17	Cleaned up tables(removed double printing)
pp.1-51 to 1-76	Updated Tables
pp.1-79 to 1-86	Updated Tables

Chapter 2

<i>Updated Page/s</i>	<i>Update Reason</i>
p. 2-8	Cleaned up tables(removed double printing)

Chapter 3

<i>Updated Page/s</i>	<i>Update Reason</i>
pp. 3-11 to 3-19	Updated Tables

Chapter 4

No Changes

Chapter 5

<i>Updated Page/s</i>	<i>Update Reason</i>
p. 5-8	Cleaned Up Table
p. 5-9	Added note Regarding Embedded Column
p. 5-31	Cleaned Up Table

Chapter 6

<i>Updated Page/s</i>	<i>Update Reason</i>
pp. 6-6 to 6-9	Added note Regarding Embedded Column

Chapters 7-9

No Changes Made

Appendix A

<i>Updated Page/s</i>	<i>Update Reason</i>
p. a-a	Alloy Table Revised

Appendix C

<i>Updated Page/s</i>	<i>Update Reason</i>
pp. C-1 to C-38	Updated Tables
pp. C-57 to C-64	Updated Tables

Appendix D

<i>Updated Page/s</i>	<i>Update Reason</i>
All Pages	are new. Chapter 1 Span Tables using 6061T6 or 6005T5